FILE NO PAGE 404

UNITED STATES PUBLIC LAND SURVEY CORNERCER	441914	SLSI 9-94
OF PHYLLIS M. OF JACKSON COL	GERLACH	# 000
	DER &	16 (b.
Land Survey Monuments situated in Section 34, Township 85 4 E., of the Fifth Principal Meridian, Tackson in Co	County Record	, Range nty, Iowa. er's Office
(book, page, document number, etc.) (Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the		
mentation found or placed.) Monument Description and Remarks: SET 5/8" Capped rods at Prore		
existing monumentation. Fences and Occupation within	this	
and adjoining Sections.		

PLAN - VIEW		.ttt awatita
(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical of recovery of the corner.)	onditions that w	/III chadic
SE COR. NE 1/4, NW 1/4 SEC. 34-85-4 *	34	
		= =
Mail + Flasher on Tot of Wood 19		
nail & Flasher on Top of Wood	Brace Ast	Λ
Mail & Flasher in 8" OAK - 3.15.		\bigcup
SET Capped 5/8" Rod		
		N.
*		Î
SW COR. NE 1/4, NW 1/4 SEC. 34-85-4		\uparrow
nail of Flasher in 6"Treenail of Flasher in 4". Ever other Tree		
()		V 1
SET 5/8" CAPPED ROD OD		
SE COR NEW, NW 14 SEC. 34-85-4 / 685- 9.4 W. of FAC. 13.6 N. of FAC. COR.		
nail & Flasher In File. 1851		
I hereby certify that the survey work was completed and this land surveying document was prepared by me or under my direct personal Corners Section	to be Indexed Twp	Range
supervision and that I am a duly registered land surveyor under the		
NE NW 34	T85N	R4E

NE' NW'	34	T85N	R4E
SW Corner		# #	
NE¼ NW¼	34	T85N	R4E
		*	

Book 1 Page 404