






LAND CORNER SURVEY











ELE NO 04-2681

OL JUN 10 PM 1:39

PREPARED BY: EGGER ENGINEERING AND LAND SURVEYING, P.C. 2395 TECH DRIVE SUITE 2 BETTENDORF, 10WA 52722 563-332-6330

PHYLLIS M. GERLACH JACKSON COUNTY, 10WA RECORDER 00

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

8	OF			
Land Survey Monuments situated in Section 3 Tow Meridian, Jack son County, Iowa. Previous in County Recorder's Office. (Show reason for preparing this certificate, the evidence and detamonumentation found or placed.) Monument Description and Remarks: Monument Center of Jection 3/-84N-	siled procedures used in es Set 5/8 " \$ 7 -4-E - USED		nher, etc.) ner positions an at the	nd 10 10 RAIGHT
Set 5/8" IRO With Cap# 49.65	SECTION N ROD 7985	I physical condition	ons that will en	able
hereby certify that the survey work was completed and his certificate was prepared by me or under my direct upervision and that I am a duly registered land urveyor under the laws of the state of lowa. ignature: CLCLS Grape No. 7983 Pate: JAMES L. Egger L.S. Pate: JAMES L. EGGER OF TOWN AND SCHOOL T	Corners Center	List Corners to Section 31	Twp	Range 4E

2

102

TLE NO 04-1869

EGGER ENGINEERING AND LAND SURVEYING, P.C.

2395 TECH DRIVE SUITE 2 BETTENDORF, IOWA 52722 563-332-6330

FIFTLIS M. GERLACH
ACKSON COUNTY, IOWA
RECORDER
UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

FOR FROM N4 JUN 22 AM 9: 07 PREPARED BY: EGGER ENGINEERING AND LAND SURVEYING, P.C. Land Survey Monuments situated in Section 3 __, Township <u>84N</u>, Range <u>4E</u>, of the Fifth Principal County, Iowa. Previously recorded in E1/4 COR BK2 Pg 176 JACKSON in County Recorder's Office. (book, page, document number, etc.) (Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) Monument Description and Remarks: EYA COR WAS NEVER SET SINCE IT WAS TILLABLE IT WAS SET USING 176 NE COR - NWY4 - SEYA WAS USING AN EXISTING EYA COR ALONG WITH UA EXISTING E-W PLAN - VIEW (Show a minimum of three reference ties to durable physical object, relevant monuments and physical conditions that will enable recovery of the corner.) NAILS IN ENCE W 11AM 410 "85 N 89° 36' 33"W NAILS IN 1315.03 FENCE POST X NAILS DISTANCES ARE N B"DIA NE COR SPPI F HORIZONTAL TREE MEASUREMENTS NW/4-5E1/4 SEC. 31-84-4 SET 5/8" 1200 WITH CAP 7983 SET 5/8" IRON ROD WITH CAP 7983 hereby certify that the survey work was completed and List Corners to be Indexed is certificate was prepared by me or under my direct Corners Section Twp Range upervision and that I am a duly registered land urveyor under the laws of the state of Iowa. 4E 31 840 E1/4. James L. Egger L.S. NE-NWY4-SEY4 840 Rcg. No. 7983 JAMES I EAL EGGER 7983

Book 2 Page 292

/OWA