UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Or .
Land Survey Monuments situated in Section 23 , Township 85N
Previously recorded in County Jove
(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monument Description and Remarks:
county records and as shown on county road construction plans.
NE Corner: Found '5" iron rod in acceptable location as set by county surveyor after road construction, using information as shown on road plans.
(Show a minimum of three reference ties to durable plants)
(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable
VE Cor. Sp. No. 24 P. P.
Found 2" Rod In N. Ditch
Sta. 58+34,62
Sta, 31+79,75
4.05' <u>\$ E-17</u>
Set 20d Nail Wwasher in Conc.
Nail G. P. St. Post


I hereby certify that the survey work was completed and this land surveying document was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa

Signature: W. lian D. Upmeyer William D. Upmeyer Name typed or printed:

Date: 6-26-96. Reg. No.

My registration renewal detections

SEAL



Corners Corners to be Indexed Section Twp			Danue
N 4	2311	85N	Range 4E
NE	23	85N	4 E

003813 FILE NO BOOK_L PAGE 284

1996 JUL -3 PM 2: 52

SHIRLY RITENOUR JACKSON COUNTY, OWA RECORDER



Document 07-1794

Book 2 Page 556 Type 15 001 Pages 1 Date 4/10/2007 Time 10:40 AM Rec Amt \$7.00

ARLENE SCHAUF, RECORDER JACKSON COUNTY 10WA

PREPARED BY: MICHAEL J. WEBER, WEBER SURVEYING, LLC, 26789 46TH AVE, BERNARD, IA 52032 (563) 879-4173

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 23, TOWNSHIP 85 NORTH, RANGE 4 EAST OF THE FIFTH PRINCIPAL MERIDIAN, JACKSON COUNTY, IOWA.

PREVIOUSLY RECORDED NONE UNLESS OTHERWISE NOTED

(book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks:

-N 1/4 COR, SEC. 23, T.85N. R.4E OF THE 5TH P.M. FOUND NAIL IN CONCRETE PER SECTION CORNER CERTIFICATE IN BOOK 1, PAGE 284, ESTABLISHED NEW TIES
-SW COR, NE-SE, SEC. 23, T.85N. R.4E OF THE 5TH P.M. PLACED 5/8' DIA REROD W/ORANGE CAP NO. 15084, ESTABLISHED CORNER USING EXISTING OCCUPATION FENCELINE CORNER
-SW COR, SE-SE, SEC. 23, T.85N. R.4E OF THE 5TH P.M. FOUND 5/8' DIA REROD W/YELLOW CAP NO. 11084 AS SHOWN IN PLAT BOOK 1-I PG 130, INSTR. NO. 97-211

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

PLAN - VIEW





DWG. NO. CLASEN



I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYING HINDER THE LAVS OF THE STATE OF THAT AND SURVEYING HINDER THE LAVS OF THE STATE OF THAT

LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

MICHAEL J. WEBER (DATE)

LICENSE NUMBER 15084

MY LICENSE RENEWAL DATE IS DECEMBER 31, 2007
SHEETS COVERED BY THIS SEAL: