




# Sec. 28






















Document 09-2136

Book 2 Page 675 Type 15 001 Pages | Date 6/03/2009 Time 11:21 AM Rec Amt \$7.00

ARLENE SCHAUF, RECORDER/REGISTRAR JACKSON COUNTY IOWA

PREPARED BY: MICHAEL J. WEBER, WEBER SURVEYING, LLC, 26789 46TH AVE, BERNARD, IA 52032 (563) 879-4173

# UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 28, TOWNSHIP 86 NORTH, RANGE 4 EAST OF THE FIFTH PRINCIPAL MERIDIAN, JACKSON COUNTY, IOWA.
PREVIOUSLY RECORDED NONE UNLESS OTHERWISE NOTED (book, page, document number, etc.)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) Monument Description and Remarks:


-S 1/4 COR. SEC. 28, T.86N. R.4E. OF THE 5TH P.M. FOUND RAILROAD RAIL AS SHOWN ON SECTION CORNER TIE SHEETS BY THE IDOT FOR HIGHWAY NO. 62

-SE COR, SEC. 28, T.86N, R.4E. OF THE 5TH P.M. FOUND  $1/2^{\prime\prime}$  REROD IN CONCRETE MONUMENT AS SHOWN ON SECTION CORNER TIE SHEETS BY THE IDOT FOR HIGHWAY NO. 62

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

PLAN - VIFW





DWG. NO. KILBURG



I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSED LAND SURVEYOR UNDER THE LAWS OF THE STATE OF IOWA.

Michael May 21, 2009

MICHAEL J. WEBER LICENSE NUMBER 15084

May 21, 2009

(DATE)

MY LICENSE RENEWAL DATE IS DECEMBER 31, 2009

THIS SHEET SHEETS COVERED BY THIS SEAL :

List Corners to be Indexed Sec Twp Range Corner

S 1/4 COR. 28 86N 4E 28 86N 4E

Book 2 Page 675

SE COR.



Book 3 Page 107 Type 15 001 Pages 1 Date 8/13/2013 Time 9:53 AM Rec Amt \$7.00

## ARLENE SCHAUF, RECORDER/REGISTRAR JACKSON COUNTY 10WA Scott A. Steinfadt PLS, Ryken Engineering, 739 Park Avenue, Ackley, Iowa 50601 - Ph. 641-847-3273 - Fax 641-847-2303 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF Land Survey Monuments situated in Section , Township 28 86 North. East, of the Fifth Principal Meridian, Jackson County, Iowa, Previously recorded in Book 2 Page 697 in County Recorder's Office This corner was used for a survey in this section for Joshua J. and Angela L. Scheckel. Basis of bearing for this corner certificate can be found on the associated plats of survey filed in the County Recorder's BC = Iron Nail with Bottle Cap BP = Brace Post CP = Corner Post CMP = Corrugated Metal Pipe CM = 4" Sq Concrete Monument with ½"ø Legend = Inside Diameter = Outside Diameter = Power Pole R/W = Iron ROW Roll R/W = Iron ROW Roil SFP = Steel 'T' Post SW = Iron Noil with Square Metal Washer TP = Telephone Pedestal TW = Iron Noil with Round Metal Washer WFP = Wood Fence Post X = Iron "X" Noils PP = Power Pole PW = Iron Nail with Plastic Washer RCP = Reinforced Concrete Pipe RH = Red Head (Iron Nail in wire) RW = Iron Nail with Reflective Round Washer ROW = Right of Way = 4 Sq Concrete Monument with ½ iron rerod in center (tie to rerod) = Cut 'K' = Gate Post = %"ø x 2.0' Iron Rerod IR SE Cor. W1/2 SW1/4 Set Witness Corner -¼"ø x 1.3' Red Capped Iron Rerod (#14677) 196.66

Set Witness Corner -14"ø x 2.0' Red Copped Iron Rerod (#14677) 49 40'

DRIVEWAY

130.00

Found ¼ o Red Capped Iron Rerod (#14677)

SE Cor. W1/2 SW1/4 - History of Corner =

2009, Dec. 11 — '¾" o x 24" Red Capped Iron Rerod (#14677)' per County Recorder's Book 1—T Page 21.
2009, Dec. 11 — 'set a ¾" o x 2.0' red capped (#14677) iron rerod' per County Recorder's Book 2 Page 697.

Current County Engineer's ties match County Recorder's Book 2 Pages 697.

Area has been cleared and lowered by approximately 15.0° by heavy equipment since original monument was set. Therefore set ¾"ø x 2.0° Red Capped Iron Rerod (#14677), flush using one remaining record tie and coordinates from 2009 Survey. All ties are plumb

This certificate is being prepared because there is a change to monumentation of record.



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed land Surveyor under the laws of the State of lowa.

Scott a Stenfadt, P.S. SCOTT A STEINFADT, PLS.

Date: 07/19/2013 License number: 14677 My license renewal date is December 31, 2014

Pages or sheets covered by this seal: \_\_\_

			Corn	ers	to	be	Indexed	
Corners		;	Section				Twp	Range
SE	Cor.	W1/2	SW1/4	28	3		86N	4E

Page 1 of 1

P:\6302\CADD\SURVEY\6302CERT.DWG

Book 3 Page 108 Type 15 001 Pages 2 Date 8/13/2013 Time 9:54 AM Rec Amt \$12.00

ARLENE SCHAUF, RECORDER/REGISTRAR JACKSON COUNTY IOWA

Scott A. Steinfadt PLS, Ryken Engineering, 739 Park Avenue, Ackley, Iowa 50601 - Ph. 641-847-3273 - Fax 641-847-2303

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 28 , Township North, East, of the Fifth Principal Meridian, Jackson County, Iowa, (see below)

Previously recorded in NW Corner - Book 2 Pages 138 & 601

All Others - Not Applicable

These corners were used for a survey in this section for Melvin J. Wagner Revocable Trust U/A/D July 12, 2010. Basis of bearing for this corner certificate can be found on the associated plats of survey filed in the County Recorder's Office for this section.

= Iron Nail with Bottle Cap

BC = Iron Noil with Bottle Cap
BP = Brace Post
CP = Corner Post
CMP = Corrugated Metal Pipe
CM = 4" Sq Concrete Monument with ½" or iron rerod in center (tie to rerod)
CX = Cut 'x'
GP = Gate Post
DR = 5" or 20" (see Pose

IR

= \( \frac{1}{8} \) \( \psi \times 2.0' \) Iron Rerod


Legend

ID = Inside Diameter
OD = Outside Diameter
PP = Power Pole
PW = Iron Noil with Plastic Washer
RCP = Reinforced Concrete Pipe
RH = Red Head (Iron Noil in wire)
RW = Iron Noil with Reflective Round Washer
ROW = Right of Way

in County Recorder's Office

R/W = Iron ROW Roil
SFP = Steel 'T' Post
SW = Iron Noil with Square Metal Washer
TP = Telephone Pedestal
TW = Iron Noil with Round Metal Washer
WFP = Wood Fence Post
X = Iron "X" Noils

## **NW** Corner



NW Corner - History of Corner =

NW Comer - History of Corner =
1998, Dec. 3 - "Set Iron Rod" per County Recorder's Book 1-J Book 128.
1998, Dec. 22 - "Set Iron Rod" per County Recorder's Book 1-K Book 6.
2001, Jan. 11 - "Set Iron Rod" per County Recorder's Book 1-L Book 106.
2003, Mar. 31 - 'SET 5%" X 36" IRON ROD WITH ORANGE CAP NO. 10134' per County Recorder's Book 2 Page 138.
2004, Feb. 6 - "FOUND IRON ROD" per County Recorder's Book 2 Page 601.
2008, Jan. 28 - '%" REBAR WAS FOUND' per County Recorder's Book 2 Page 601.
2009, Current County Engineer's ties match County Recorder's Book 2 Pages 138 and 601.

Conter Recovery = Searched area near intersection of record ties with a magnetic locator, excavated a  $1.0^{\circ}$ 0 x  $1.0^{\circ}$  deep hole at magnetic reading. Found a  $\frac{9}{8}^{\circ}$ 0 x  $36^{\circ}$ 1 iron rerod lying flat,  $1.0^{\circ}$ 3 deep in slide area on edge of dry ditch and  $1.5^{\circ}$ 2 north of fenceline east — west. Location of manument found matches that of record. Therefore, reset rerod using distances from record ties,  $1.4^{\circ}$  exposed, placed limestone slabs around rerod to the top for erosion protection only. All ties are

This certificate is being prepared because there is a change to monumentation of record.



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lowa.

SCOTT A. STEINFADT, PLS

Date: 07/19/20(3 License number: 14677

My license renewal date is December 31, 2014

Pages or sheets covered by this seal: \_\_\_\_1, 2

Г	C		1 1 1 1	
	Corr	ners to	be Indexed	
	Corners	Section	Twp	Range
	NW Corner	28	86N	4E
	NW Cor. E/2 NW1/4	28	86N	4E
	N¼ Corner	28	86N	4E
	Center	28	86N	4E
	W¼ Corner	28	86N	4E

Page 1 of 2

P:\6302\CADD\SURVEY\6302CERT.DWG

## NW Cor. E1/2 NW1/4 Driveway Found Iron Spike in S. Face WFP (Tie to Head) Gravel 88 Found Iron Spike in Top RR Tie End Post (Tie to Center of Head) n Telephone Pedestal

### NW Cor. E1/2 NW1/4 - History of Corner =

"RR SPIKE IN ROCK OUTCROPPING" per County 2004, Feb. 6 -Recorder's Book 1-0 Page 33.

Current County Engineer's ties do not indicate that corner is

#### Corner Recovery =

Searched area near fence intersections as indicated of the 2004 Survey with a magnetic locator. Found an iron RR spike, flush in surface of gravel driveway, 7.5'± east of apparent centerline of traveled surface of gravel driveway, 7.5'± east of fenceline north and 21.0'± north of fenceline west. Location of monument found matches that of record, monument found matches that of record. Therefore, used iron RR spike as the correct corner. All ties are numb distance. ties are plumb distance.

This certificate is being prepared because there are no certificates on file for this corner.

## N¼ Corner



Set TW in 8"# Elm Tree, 1.0'± above ground

N¼ Corner - History of Corner =


Current County Engineer's ties do not indicate that corner is monumented.

#### Corner Recovery =

Calculated a location for the N¼ Corner by intersecting a line from the S¼ Corner through the Center of Section with a line from the NW Corner through the NW Cor. E1/2 NW1/4. Searched area with a magnetic locator, excavated a 1.0  $\!\!\!/\!\!\!/ e \times 1.5'$  deep hole at magnetic reading. Found fence wire running north — south and several small limestone cobbles, 1.0'± deep. Said calculated location is in-line with fenceline South. Therefore since no available County records indicate monumentation of the N% Corner and no monumentation could be located, set a ¾"ø x 4.0' aluminum capped iron rerod (#14677), flush at said calculated location. Also searched with a magnetic locator, an area at a point online and double the distance between said NW Corner and said NE Cor. E½ NW¼ to the east and found no magnetic readings. This location was not accepted as it falls 35.0°± east of an existing fence running south. All ties are plumb distance

This certificate is being prepared because there are no certificates on file for this corner.

### Center



### Center - History of Corner =

1988, Feb. 13 -County Recorder's Book 1-F Page 147 indicates usage of corner but not type of monumentation.


Current County Engineer's ties do not indicate that corner is monumented.

## Corner Recovery =

Searched an area visually, with a magnetic locator and a tile probe at record distances west from fence intersections shown on the 1988 survey and found an old RR tie corner post (leaning MWI/y). Since there are no available County records indicating monumentation of corner and fence corner is the best available evidence of corner location, set a ¾"ø x 4.0' aluminum capped iron rerod (#14677), 0.9' exposed on the Southeast side of said RR tie corner post in-line with fencelines north, east and west. All ties are plumb distance.

This certificate is being prepared because there are no certificates on file for this corner.

## W¼ Corner



W1/4 Corner - History of Corner =

Current County Engineer's ties do not indicate that corner is monumented

#### Corner Recovery =

Searched area around a 3 way fence intersection with a nagnetic locator and tile probe. Excavated a 1.5' ø x 1.5' deep hole around a new wood corner post and found wood fibers and very old fence wire on the east side of post. Also found a rotted off round corner post tied with fence wire to a rotten RR tie corner post south of new corner post, if the fence connecting the two rotten corner posts is stretched tight the base of the rotted round post would have been on very near the new corner post. Therefore since there are no available County new corner post. Therefore since there are no available Coun records indicating monumentation of Corner and fenceline evidence is the best available evidence of the Corner location, and the corner fencel fence are for fencel fencel. evidence is the best available evidence of the Corner location, set a  $\frac{3}{4}$ "ø x 4.0' aluminum capped iron rerod (#14677), 0.4' exposed on the east side of said new corner post through very old fence wire and wood fibers. Monument set is in-line with fences south, east and west. All ties are plumb distance.

This certificate is being prepared because there are no certificates on file for this corner.

## Legend

= Iron Nail with Bottle Cap
= Brace Post
= Corner Post
= Corrugated Metal Pipe
= 4" Sq Concrete Monument with ½"ø

CM ron rerod in center (tie to rerod)
Cut 'X'
Gate Post

%"ø x 2.0' Iron Rerod

Inside Diameter

ID = Inside Diameter

DD = Outside Diameter

PP = Power Pole

PW = Iron Noil with Plastic Washer

RCP = Reinforced Concrete Pipe

RH = Red Head (Iron Noil in wire)

RW = Iron Noil with Reflective Round Washer

ROW = Right of Way

 R/W =
 Iron ROW Roil

 SFP =
 Steel 'T' Post

 SW =
 Iron Noil with Squore Metal Washer

 TP =
 Telephone Pedestal

 TW =
 Iron Noil with Round Metal Washer

 WFP =
 Wood Fence Post

 X =
 Iron "X" Noils

Page 2 of 2

P:\6302\CADD\SURVEY\6302CERT.DWG