
Sec. 32



LAND CORNER SURVEY

JACKSON COUNTY T85 & 86 N R4E


MADE FOR


IOWA STATE HIGHWAY COMMISSION


FOR ROW DESCRIPTIONS ON PRIMARY 113 PROJECT FN 830 A-1


SUNE JULY 1941


See field notes filed in Ames office for complete
Information.















































UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

| Land Survey Monuments situated in Section 32 4E, of the Fifth Principal Meridian, Previously recorded in | 2 | Township | 86N | D |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|--------------------|-----------------------------|----------------------|
| 10001dcd III | | Township | C | , Range ounty, Iowa. |
| (Show reason for preparing this certificate, the evidence and detaile mentation found or placed.) Monument Description and Remarks: | ed procedures u | sed in establishin | m ('anna- D | |
| SE COR. = "X" IN TOP OF FOUND LIMESTO | ONE OUT | | | |
| - 100 OT TOOND LIMES TO | ONE OVER | IRON PIN | | |
| | | | | |
| | | | | |
| | | | | · · |
| (Show a minimum of three reference time) | VIEW | | | |
| (Show a minimum of three reference ties to durable physical objects recovery of the corner.) | s, relevant mon | uments and phys | ical conditions th | at will enable |
| | | 1 . | <u> </u> | |
| i i | N.F. IN | I U,P. | ┝╼┾╼┼╾┤ | |
| | 5 | | 32 | - |
| 6 | | | | ' |
| * | | . / * | | |
| | | | | |
| 1 | 60 | | | |
| 1 | 101,06' | | | . (|
| "X" IN TOP OF LIMESTONE (OVER IRON PIN) AT THE | | | | |
| SE COR. OF SEC. 32-86-4 | | ļ. | | |
| | -8 -8 -900000 | -5 | 0VER LIMESTO | NE (OVER ID) |
| 27, | .68' | r-9°→ | . AT THE NE CO | OR. SEC A |
| | | | 9 | , |
| | | | | |
| SE CORNER | | | | * |
| | | ! * . | | |
| 12 | 20,18' | i ' | 19 | |
| 9 | | | | |
| | , | 1 | | |
| ž | | A N | I.F. IN U.P. | |
| | | Ψ. | | |
| I hereby certify that the survey work was completed and this certificat was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the man of the laws of the control of the laws of t | ite | Tio C | | |
| I am a duly registered land surveyor under the laws of the state of | Corne | ers Section | ers to be Indexed Twp | Range |
| Signature: FV / // | SE C | COR. 32 | 86 | 4 |
| Name typed or printed: LAVERNE F. VANDER SCHMITT | - | | | |
| Reg. No. //084 | | (*) | | |
| none of NL LANdere | _ | | | |
| A CONTRACTOR OF THE PROPERTY O | | | | |
| LaVerne F Vander Schaaf | - | 200 M | m 0030 | פכינ |
| SEAL O Valloer Schaaf III | a a | FILE 2001 | - 110 | |
| | | [99] | APR 27 AH | |
| "and of OW A There of the of t | | | | |
| | | S JACI | HIRLY RITEHO KSON COUNTY | UR LOWA |

Document 06-1007

Book 2 Page 433 Type 06 023 Pages 1 Date 3/15/2006 Time 1:37 PM Rec Amt \$7.00

PHYLLIS M. GERLACH, RECORDER JACKSON COUNTY LOWA

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 128 Farley, Iowa 52046 563-744-3631

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 32, Township 86 North, Range 4 East of the Fifth Principal Meridian, Jackson County, Iowa.

Previously recorded

(NONE OF RECORD)
(BOOK, PAGE / INST. NO. / CABINET, SLIDE)


(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and

Monument Description and Remarks: A CONCRETE MONUMENT WITH AN EMBEDDED 1/2" REBAR WAS FOUND AT THE W1/4 CORNER OF SECTION 32 TB6N R4E AS ILLUSTRATED ON I.D.O.T. CORNER TIES FOR PROJECT F-144 DATED IN 1958 A CONC. MONUMENT WITH AN EMBEDDED 1/2" REBAR WAS FOUND NEAR THE SW CORNER OF SECTION 32, T86N, R4E AS ILLUSTRATED ON I.D.O.T. CORNER TIES FOR PROJECT F-144. THE MONUMENT AND TIES DID NOT TAKE INTO ACCOUNT THERE WERE TO BE DOUBLE SET OF CORNERS ON THE CORRECTION LINE AS INDICATED ON OLDER I.D.O.T. TIES. #14417 WAS SET AS INDICATED ON THE OLDER I.D.O.T. TIES OBTAINED AT THE JACKSON COUNTY ENGINEER'S OFFICE


PLAN - VIEW

SET 'X' NAILS ON TOP OF FENCE POST

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



W1/4 CORNER SEC.32, T86N, R4E FOUND CONC. MONUMENT W/ 1/2" REBAR



FOUND CONC. MONUMENTS W/ 1/2" REBAR 982.58 AL

541.42 27.01-₩**1**9.80 FOUND CONC. MONUMENT W/ 1/2" REBAR NW CORNER— SEC.5, T85N, R4E SET 1/2" REBAR W/ YELLOW CAP #14417

FOUND R.O.W. RAIL

527

0

NAILS ON TOP OF BRACE POST

SW CORNER SEC. 32, T86N, R4E SET 1/2" REBAR W/ YELLOW CAP #14417

I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

David P. Schneider #14417

Date: My license renewal date is December 31, 2007.

Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER

Land Surveying & Planning, Inc.

P.O. Box 128 Farley, Iowa 52046 Ph. #563-744-3631 Fax#563-744-3629



| = | | | | | | |
|---|-----------|-----------|----|----|------------|-------|
| | Lis | t Corners | to | be | Indexed | |
| | Corners | Section | | T | ∢ p | Range |
| | W1/4 | 32 | | 86 | N | 4E |
| | SW CORNER | 32 | | 86 | N | 4E |