

Book 2 Page 656 Type 15 001 Pages 1 Date 1/29/2009 Time 2:39 PM Rec Amt \$7.00

ARLENE SCHAUF, RECORDER/REGISTRAR JACKSON COUNTY IOWA

PREPARED BY MICHAEL J. WEBER, WEBER SURVEYING, LLC, 26789 46TH AVE, BERNARD, IA 52032 (563) 879-4173

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 36, TOWNSHIP 86 NORTH, RANGE 1 EAST OF THE FIFTH PRINCIPAL MERIDIAN, JACKSON COUNTY, IOWA.

PREVIOUSLY RECORDED NONE UNLESS OTHERWISE NOTED (book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)


Monument Description and Remarks:


-CENTER SEC. 36, T.86N. R.1E. OF THE 5TH P.M. PLACED 5/8" REROD W/ORANGE CAP MARKED "WEBER PLS 15084", ESTABLISHED CORNER AT THE INTESECTION OF OCCUPATION FENCELINES RUNNING EAST, WEST & SOUTH.

-NORTH 1/4 CORNER SEC. 36, T.86N. R.1E. OF THE 5TH P.M. PLACED 5/8'' REROD W/GRANGE CAP MARKED "WEBER PLS 15084" ESTABLISHED CORNER AT THE INTERSECTION OF THE FENCELINE NORTH AND THE SOUTH LINE EXTENDED WEST OF THE PLAT SHOWN IN PLAT BOOK 1-F PAGE 94.

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

PLAN - VIEW





DWG. NO. KNUTH



I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSER LAND SURVEYOR UNDER THE LAVS OF THE STATE OF IDVA.

Michael J. Weber (Date)


LICENSE NUMBER 15084

MY LICENSE RENEWAL DATE IS DECEMBER 31, 2009 SHEETS COVERED BY THIS SEAL :

List Corners to be Indexed Sec Twp Range

NORTH 1/4 36 86N 1E CENTER 36 86N 1E

Book 2 Page 656



Jones County Engineer's Office P.O. Box 368 Anamosa, Iowa 52205 ATTN: Clarence J. Walton, LS

Clark Schloz, P.E. County Engineer Jackson County, Iowa Jackson County Courthouse 201 West Platt Street Maquoketa, Iowa 52060

RE: Section Corner Certificates and attending photos

Dear Clark:

Enclosed please find a copy of the Section Corner Certificates that we recorded as a document here in Jones County. Also, we took some photos to aid in following the certificate's narratives.

If you, or your staff have any questions, please call me, I am at your service. Thank you for your kind attention to this.

Sincerely,

Clarence J. Walton

Jones County Marie Krutzfield, Recorder Fee Book 2010 1018

Fee Book 20-04/23/2010 @0231PM ZSC SEC COR CERT Booki Fees: \$0.00

Pages: 4


PREPARED BY

CLARENCE J. WALTON JUNE COUNTY ENGINEER'S OFFICE, 19501 HWY. 64, ANAMOSA, IOWA, 52205 (319) 462-3785

COVER SHEET

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 36, TOWNSHIP 86 NORTH, RANGE 1 WEST OF THE 5TH PRINCIPAL MERIDIAN, JONES COUNTY, IOWA.





I hereby certify that this land surveying document and the related survey work was performed by me or under my direct personal supervision and that I am a duly registered Land Surveyor under the laws of the State of Iowa.

Signed:

Clarence J. Walton, L.S.
Watton, L.S.
Watton, L.S.
Watton & S.
Wat

Pages or sheets covered by this seal: 1 of 1.


JONES COUNTY ENGINEER'S OFFICE



19501 HWY. 64, ANAMOSA, IOWA 52205 (319) 462-3785

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 36, TOWNSHIP 86 NORTH, RANGE 1 WEST OF THE 5TH PRINCIPAL MERIDIAN, JONES COUNTY, IOWA.



PREVIOUSLY RECORDED IN BOOK 2, PAGE 354, JACKSON COUNTY RECORDER'S OFFICE AND IN BOOK 301, PAGE 25 IN THE JONES COUNTY, IOWA RECORDER'S OFFICE.

MONUMENT DESCRIPTION AND HOW ESTABLISHED FOUND 16"X14"X4" LIMESTONE STANDING ON EDGE, THE TOP 5" OF WHICH IS ABOVE PRESENT GROUND LEVEL. STONE'S LONG AXIS IS ORIENTED NORTH AND SOUTH. SCRAPED GROUND BELOW STONE FOR EVIDENCE OF ORIGINAL POST, NONE FOUND. SET TWO 5/8" REBAR W/ ORANGE PLASTIC CAPS #11310 AT THE NE AND SE CORNERS OF STONE TO PREVENT STONE FROM FALLING SIDEWAYS AND FOR A MAGNETIC SIGNATURE. STONE IS IN CLOSE PROXIMITY TO FALLEN FENCE AND TO OLD CEDAR CORNER POST. A STEEL FENCE POST WITH A YELLOW JONES COUNTY "SURVEY MARKER" SIGN WAS SET APPROXIMATELY 8" EAST OF STONE AS A WITNESS POST. AS THERE IS NO RECORD OF THE STONE'S "PEDIGREE" WE RETRACED THE ORIGINAL GOVERNMENT SURVEY NOTES TO SEE IF THERE WAS ANY COLLABORATION OF EVIDENCE AS TO THE STONE'S POSITION IN REGARD TO THE GOVERNMENT NOTES. WE MEASURED A DISTANCE OF 62.70' TO THE CENTER OF A 45" WHITE OAK SW OF THE STONE WHICH AGREED WITH THE ORIGINAL GOVERNMENT SURVEY NOTES. ASSUMING THE EAST LINE OF SAID SECTION 36 (THE 5TH PRINCIPAL MERIDIAN, AS MONUMENTED BY FOUND STONES AT THE NE & SE CORNERS OF SAID SECTION 36) TO RUN TRUE NORTH (WHICH IS WHAT BURT RAN), THE BEARING TO THE CENTER OF THE BEARING TREE WAS S76'40'28"W. THE GOVERNMENT NOTES CALL FOR S76'W. NO SCARS WERE APPARENT WITHOUT LETTING THE IMAGINATION RUN AWAY, THE ORIGINAL GOVERNMENT NOTES RECITED THAT THE OAK WAS 10' IN DIAMETER (ca 1836) . WITH THE PRESENT DIAMETER BEING 45", THE GROWTH RATE WAS AN AVERAGE OF 0.2" PER YEAR, THIS FALLS RIGHT IN LINE WITH THE NOMINAL GROWTH RATE FOR A WHITE OAK. WE WERE ALSO FORTUNATE TO HAVE A VERY DISTINCTIVE CALLED FOR NATURAL MONUMENT IN THE FORM OF THE "FOOT OF PERPDR [PERPENDICULAR AUTHOR'S NOTE] LIME ROCK 50 FT. HIGH". THIS IS VERBATIM FROM THE ORIGINAL FIELD NOTES. WE MEASURED 461' FROM WHERE WE THOUGHT THE FOOT WAS AND FOUND WE WERE WITHIN ±4' OF WHAT THE GOVERNMENT NOTES SHOWED. THUS THE FOUND STONE'S LOCATION IS IN ALL LIKELYHOOD WHERE THE ORIGINAL SURVEYOR SET THE POST. QUITE LIKELY WHOEVER SET THE STONE HAD ACTUALLY REPLACED THE SECTION CORNER POST WITH THE STONE OR USED THE GOVT FIELD NOTES.

FIELD BOOK 344, PAGE 78. DATE OF SURVEY: 10/9/09 I hereby certify that this land surveying document A. THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED. and the related survey work was performed by me or under my direct personal supervision and that I am a duly registered Land Surveyor under the laws of the State of Iowa. B. THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED. CLARENCE C. THE SURVEYOR IN RESPONSIBLE CHARGE OF THE LAND SURVEYING ACCEPTS A CORNER POSITION THAT DIFFERS FROM THAT SHOWN IN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER IS WALTON 1. 4 11310 Clarence J., Walton, L.S.
Watton, L.S.
My Registration Renewal Date is December 10wa License Number 11310
Pages or sheets covered by this seal: 1 of 1. □ D. THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD E. EXISTING CORNER TIES UPDATED. CORNERS TO BE INDEXED JONES COUNTY ENGINEER'S OFFICE SECTION CORNER TOWNSHIP RANGE NE CORNER 36 1W

SE CORNER

NW CORNER

SW CORNER

25

6

31

86N

85N

85N

1W

1E

1E



19501 HWY. 64, ANAMOSA, IOWA 52205 (319) 462-3785

SECTION 36-T86N-R1W **NE CORNER**

VIEW IS LOOKING SOUTHEAST. FOUND 16**

14** X. 41** X. 41** ENESTONE SET ON EDGE. TO THE LEFT OF THE STONE, AN OLD RED CEDAR CORNER POST THAT WE LIFTED OFF THE GROUND NOD SET UP CAN BE SEEN WITH WIRE RUNNING NORTH (LEFT) AND SOUTH (RIGHT) AND EAST FENCE WIRE ALSO RUNS WEST BURIED UNDER LEAF AND TREE LITTER. THE LONG AXIS OF THE STONE IS ORIENTED NORTH. SET FOLLOWING PAGE FOR DETAILED VIEW OF STONE.

PLEASE PROTECT

MARKER SURVEY NEARBY

IF LOCATION OF THIS MARK

ENGINEER'S OFFICE PLEASE CONTACT IS ENDANGERED JONES COUNTY 319-462-3785

"SURVEY MARKER" SIGN



VIEW IS LOOKING SOUTHEAST. 5/8" X 24"
REBARS ARE PLACED TO PROTECT
MONUMENT FROM BEING KNOCKED OVER.
ORANGE PLASTIC CAPS (OPC) EMBOSSED
WITH "JONES COUNTY IS 1310" WERE
PLACED TO PROTECT LIVESTOCK! PEOPLE
FROM LAMING THEMSELVES ON SHARP
REBAR TOPS AND FOR IDENTIFICATION OF
SURVEYOR RESPONSIBLE FOR MONUMENT
PERPETUATION. ALSO, THE BOTTOM OF
THE STEEL POST THAT HAS A "SURVEY
MARKER" SIGN ATTACHED TO IT CAN BE
SEEN. IN THE IMMEDIATE FOREGROUND.
AN OLD DOWNED FENCE RUINING SOUTH
ROUGHLY 450 FEET TO A PRECIPICE AND
TO THE NORTH WHERE IT IS SOON
OBLITERATED DUE TO BULLDOZING
ACTIVITY. THE LONG AXIS OF THE STONE
IS ORIENTED NORTH.

*SEE SKETCH OF SIGN BELOW.

"SURVEY MARKER" SIGN

PLEASE PROTECT NEARBY

TH/OPC #11310

MARKER SURVEY

IF LOCATION OF THIS MARK IS ENDANGERED PLEASE CONTACT

ENGINEER'S OFFICE JONES COUNTY

319-462-3785

NE CORNER SECTION 36-T86N-R1W **BEARING TREE FOR**

VIEW IS LOOKING WEST. CAMERA IS OVER THE STONE
AT THE NE CORNER OF SECTION 35, GSUBMING THE
EAST LINE OF SECTION 36, (THE 5¹¹ PRINCIPAL
MERIDIAN) AS MONUMENTED BY FOUND STONES AT
THE SEC CORNER OF SECTIONS AND HERE AT THE NE
CORNER TO RUN TRUE NORTH; THE BEARING AND
DISTANCE FROM THE TOP CENTER OF THE FOUND
STONE TO THE CENTER OF THE BEARING TREE WAS
FOUND TO BE ST6'40'28'W 62.70; THIS COMPARES
WELL WITH THE ORIGINAL GOVERNMENT SURVEY
NOTES, WHICH CALLS OUT THE BEARING AND
DISTANCE AS STONE OF SURVEY
NOTES, WHICH CALLS OUT THE BEARING AND
DISTANCE AS STONE
NOTES, WHICH CALLS OUT THE ERERING AND
DISTANCE AS STONE
NOTES, WHICH CALLS OUT THE ERERING AND
DISTANCE AS STONE
NOTH CORDINATES TO THE CENTER OF THE TREE
ARE AS FOLLOWS: N:3554599.15 E:560746S.96.



"SURVEY MARKER"

SIGN

PLEASE PROTECT NEARBY

作取的主义。

MARKER SURVEY

IF LOCATION OF THIS MARK ENGINEER'S OFFICE IS ENDANGERED PLEASE CONTACT JONES COUNTY

319-462-3785

PAGE 5 of 8

SECTION 36-T86N-R1W **NE CORNER**

"SURVEY MARKER" SIGN


PLEASE PROTECT NEARBY

MARKER SURVEY

IF LOCATION OF THIS MARK PLEASE CONTACT IS ENDANGERED


ENGINEER'S OFFICE JONES COUNTY

PAGE 6 of 8



UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 36, TOWNSHIP 86 NORTH, RANGE 1 WEST OF THE 5TH PRINCIPAL MERIDIAN, JONES COUNTY, IOWA.



PREVIOUSLY RECORDED IN N/A

MONUMENT DESCRIPTION AND HOW ESTABLISHED ORIGINAL GOVERNMENT FIELD NOTES STATE THAT NO POST WAS SET AT THE E 1/4 CORNER AS A 13" WHITE OAK SERVED AS A CORNER TREE. NO SIGN OF TREE COULD BE FOUND EITHER ON SURFACE OR BELOW. 1940 AERIAL PHOTO SHOWS ONLY SMALLER TREES IN THE AREA WHERE THE CORNER TREE WOULD HAVE BEEN. THE GOVERNMENT NOTES ALSO STATE THAT THE CORNER WAS 5.75 CHAINS (379.5 FEET) SOUTH OF THE "TOP OF A PRECIPICE 75 FT. HIGH" (VERBATIM FROM ORIGINAL GOVERNMENT FIELD NOTES, A 5/8" X 24" REBAR WITH AN ORANGE PLASTIC CAP #11310 WAS SET 379.5 FEET SOUTH OF THE TOP OF THE PRECIPICE (THIS POINT IS VERY DEFINITE) AND ON LINE BETWEEN A FOUND FOUND STONE AT THE SE CORNER OF SECTION 36-T86N-R1W AND A FOUND STONE AT THE NE CORNER OF SAID SECTION 36. THE CORNER, SO SET, FELL 7.46 FEET NORTH OF BEING EQUIDISTANT BETWEEN THE 2 FOUND STONES, A STEEL FENCE POST WITH A YELLOW JONES COUNTY "SURVEY MARKER" SIGN WAS SET NEXT TO THE SET SECTION CORNER AS A WITNESS. THERE WERE FLUORESCENT PINK PAINTED STEEL FENCE POSTS AND ANGLE IRONS SET ALONG NEAR THE SECTION LINE FROM THE SOUTH TO THE TOP OF THE LEFT BANK OF THE NORTH FORK OF THE MAQUOKETA RIVER TO THE NORTH. THESE POSTS WERE POSSIBLY SET TO MARK THE SECTION LINE DUE TO RECENT LOGGING ACTIVITY. EXCEPT FOR THE ORIGINAL GOVERNMENT SURVEYS, NO SURVEY RECORDS WERE FOUND TO EXPLAIN HOW THESE POSTS WERE SET.




I hereby certify that this land surveying document and the related survey work was performed by me or under my direct personal supervision and that I am a duly registered Land Surveyor under the lav of the State of lowa.

Clarence J Walton, L.S My Registration Renew

newal Date is Dece per 11310 lowa License Number 11310 Pages or sheets covered by this seal: 1 of 1.

CORNERS TO BE INDEXED

CORNER	SECTION	TOWNSHIP	RANGE
E 1/4 CORNER	36	86N	1W
W 1/4 CORNER	31	86N	1E



RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED. B. THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED.

C. THE SURVEYOR IN RESPONSIBLE CHARGE OF THE LAND SURVEYING
ACCEPTS A CORNER POSITION THAT DIFFERS FROM THAT SHOWN IN ACCEPTS A CORNER POSITION THAT DIFFERS FROM THAT SHOWN IN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER IS LOCATED.

D. THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD NO LONGER EXIST

E. EXISTING CORNER TIES UPDATED.

JONES COUNTY ENGINEER'S OFFICE



19501 HWY. 64 ANAMOSA, IOWA 52205 (319) 462-3785

SECTION 36-T86N-R1W

SIDE VIEW OF PRECIPICE **NORTH OF E 1/4 CORNER**

VIEW IS LOOKING ESELY ACROSS THE 5TH PRINCIPAL MERIDIAN, FALLEN ROCK IN FOREGROUND HIDES THE FULL VIEW OF THE VERTICAL FACE, PHOTO WAS THEWARD ABOUT 3. THE WAY UP THE BLUFF. THIS IS ROUGHLY 150 FEET WNW-LY FROM THE 5TH P.M.

SECTION 36-T86N-R1W

NORTH OF E 1/4 CORNER VIEW OF PRECIPICE

THE VIEW OF THE NORTH FACE OF THE PRECIPICE 5.75 CHAINS NORTH THE EX CONREGION SECTIONS SATIONS. THE EX CONREGION SECTIONS SATIONS SATIONS OF THE PRECIPICE SATIONS OF THE PRECIPICE OF THE PRECIPICE OF THE PRECIPICE OF THE PROMISE OF THE PRECIPICE OF THE PRECIPICE OF THE DRIVEN AND SATIONS THAT HAS SLUMPED. CLIMBING WAS DIFFICULT OUR TO UNSURE FOOTING.



NEAR TOP OF PRECIPICE NORTH OF E 1/4 CORNER SECTION 36-T86N-R1W

VIEW IS LOOKING NW-LY ACROSS THE 5TH PRINCIPAL MERIDIAN. THE STEEL FENCE POST IN THE NEAR FOREGROUND IS ON THE 5TH P.M. AND THE RIBBON DANGLED IN THE TREE SLIGHLY TO THE RIGHT AND FURTHER DOWN HILL IS ALSO ON THE 5TH P.M. THE RIBBON IS NEAR THE VERTICAL DROP. THIS IS WHERE WILLIAM AUSTIN BURT'S CREW CAME TO THE "TOP OF PRECIPICE 75 FT HIGH" (HIS WORDS) 5.75 CHAINS NORTH OF THE E % CORNER OF SECTION 35-T86N-R1W.



VIEW OF PRECIPICE NORTH OF E 1/4 CORNER SECTION 36-T86N-R1W

LOONING NORTH ALONG THE 4" PRINCHAL MERIDAN SHOWNS THE E X CORRER OF SECTION 94-TBENKFW. THE FLUORESCENT FINK PARTIES STEELS FERKE POSTS THAT WERE SET INGARY, ALAGINS THE 4" AN FROM HURAT THE FLUORESCENT FINK FOR THE WORTH FORK OF THE MADLOVERTA RUBRY TO THE ESTANK OF THE MENRE TO THE MOSTH. THE CORRIGHAL CORRER WAS A 13 MCH WHITE DAK AND SERVED AS A CORNER TREE NO SIGN OF THE RESE OF ANY OF THE TREE POSTS THAT SHOW THE THE AND SIGN OF THE TREE NO SIGN OF THE TREE AND SERVED AS A CORNER THEE NO SIGN OF THE TREE AS A 13 MCH WHATE OAK AND SERVED AS A CORNER THE NO SIGN OF THE TREE AS A 13 MCH WHATE OAK AND SERVED AS A CORNER THE TO ROBING WAS AND THE SECORNER FOUND STOWER AT THE ME CORNER OF THE ORDER THE ORDER THE ORDER THE OBJECT OF THE MOST THE ORDER THE ORDER THE OBJECT OF THE MOST THE ORDER THE ORDER THE ORDER THE OST THE SETS SOUTH OF THE ORDER THE THE TOWEN THE THE ORDER THE THE ORDER THE THE ORDER THE THE TOWEN THE THE ORDER THE THE ORDER THE THE THE ORDER THE THE THE ORDER THE THE ORDER THE THE THE THE THE ORDER THE THE THE THE THE THE THE THE ORDER THE THE T

"SURVEY MARKER" SIGN

PLEASE PROTECT NEARBY

SURVEY

IF LOCATION OF THIS MARK


MARKER

IS ENDANGERED
PLEASE CONTACT
JONES COUNTY
ENGINEER'S OFFICE

319-462-3785

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE


LAND SURVEY MONUMENTS SITUATED IN SECTION 36, TOWNSHIP 86 NORTH, RANGE 1 WEST OF THE 5TH PRINCIPAL MERIDIAN, JONES COUNTY, IOWA.



19501 HWY, 64, ANAMOSA, IOWA 52205

S 1/4 CORNER SECTION 36-T86N-R1W

VIEW IS LOOKING SOUTHEAST FROM THE MIDDLE OF SKAHILL, ROAD, FOUND STONE IS 6" X 6" X 15" POINTED, DRESSED LIMESTONE AND IS 19" BELOW PRESENT SCAD SURFACE. NOTE ORIENTATION OF STONE. THE MAJOR AXES OF THE STONE, EXCEPTING VERTICAL, RUN WITH THE CARDINAL DIRECTIONS OF THE COMPASS. TOP CENTER OF STONE IS 2.06" KAST OF FOUND ½" REBAR. 5/8" X 24" REBAR ARE STET FOR DETECTION PURPOSES ONLY AND ARE SNUGGED UP AGAINST THE NORTH AND SOUTH SIDES OF THE STONE.





Ocument 17-4053

Book 2017 Page 4053 Type 15 001 Pages 1 Date 11/15/2017 Time 2:10 PM Rec Amt \$7.00

ARLENE SCHAUF, RECORDER/REGISTRAR JACKSON COUNTY IOWA

PREPARED BY: MICHAEL J. WEBER, WEBER SURVEYING, LLC, 26789 46TH AVE, BERNARD, IA 52032 (563) 879-4173

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

LAND SURVEY MONUMENTS SITUATED IN SECTION 36, TOWNSHIP 86 NORTH, RANGE 1 EAST OF THE FIFTH PRINCIPAL MERIDIAN, JACKSON COUNTY, IOWA. PREVIOUSLY RECORDED NONE

(book, page, document number, etc.)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

-SE COR. SW-SE, SEC. 36, T.86N. R.1E. OF THE 5TH P.M. PLACED 5/8' DIA. REROD W/ORANGE PLASTIC CAP NO. 15084. ESTABLISHED CORNER MIDWAY AND ONLINE BETWEEN THE SE CORNER AND THE CALCULATED SOUTH 1/4 CORNER OF SAID SECTION 36.


(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)

PLAN - VIEW

DRAVING NOT TO SCALE

ALL TIES ARE MAG NAILS IN TOP OF WOOD POST SE COR. SW-SE, SEC. 36, T.86N. R.1E. OF THE 5TH P.M. PLACED 5/8° DIA. REROD W/DRANGE PLASTIC CAP NO. 15084

DWG. NO. 17072-OTTING



I HEREBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS PREPARED AND THE RELATED SURVEY WORK WAS PERFORMED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION AND THAT I AM A DULY LICENSON LAND SUBJECT OF THE LAYS OF THE STATE OF TOWA.

LICENSON LAND SURVEYOR, UNDER THE LAYS OF THE STATE OF TOWA.

Michael White October 11, 2017

MICHAEL J. WEBER
LICENSE NUMBER 15084

MY LICENSE RENEWAL DATE IS DECEMBER 31, 2017

SHEETS COVERED BY THIS SEAL ____ THIS SHEET

List Corners to be Indexed

orner Sec Twp Range

SE COR. SW-SE 36 86N 1E