

LAND T-84-N

CORNER

SURVEY R-2&3-E

MADE FOR IOWA STATE HIGHWAY COMMISSION FOR THE PURPOSE OF R.O.W. DESCRIPTIONS ON IOWA PRIMARY HWY. NO. 61 SOUTH OF THE TOWN OF MAQUOKETA.

HN D. FRANKLIN MADE BY

R.L.S. NO. 2051 F - 21

JOHN D. FRANKLIN JACKSON COUNTY

SEPTEMBER 1959

ALL DISTANCES WERE CAREFULLY MEASURED AND MAY NOT AGREE WITH ROAD SURVEY STATIONING.


FOR COMPLETE INFORMATION ON THIS SURVEY, SEE FIELD NOTES ON FILE IN AMES OFFICE.


I, HEREBY CERTIFY THAT THIS PLAT IS A TRUE REPRESENTATION OF A SURVEY MADE BY ME, ASSISTED BY JAMES D. FRANKLIN, R.H.JANSS, F.A.NORTON, L.R. MC GUIRE AND R. MC CREA, ALL DULY SWORN, AND IS CORRECT TO THE BEST OF MY KNOWLEDGE.


SIGNED: December 8.1959


JOHN D. FRANKLIN


R. L.S. NO. 2051























BOOK 1

PAGE 63

Converted Centification

## UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

PREVIOUSLY RECORDED IN <u>BOOK 1 PAGE</u> (Show reason for preparing this certificate, the evidence and or placed.)	detailed procedures used in establishing the corner positions and monumentation found
30 (#A)	SET 5/8" x 30" REBAR 6" DEEP AFTER COUNTY GRADING
PROJECT, USING CONSTRUCTION REFERE	
111000001	
	PLAN - VIEW
	of bolects, relevant monuments and physical conditions that will enable recovery of the
corner.)	
The state of the s	
	N I / 4 COR, OF SEC,3I
000000	SET 5/8" x 30"
O02082	REBAR W/CAP;
800K_LPAGE	
1994 JAN 20 PM 12: 11	
SHIRLY RITENOUR	
JACKSON COUNTY, 10WA	
RECORDER	43336
110 Jee	"X" NAILS IN POWERPOLE
ROA	51.50.
COUNTY ROAD	1
,   100	22/20/2
	TOP OF OUTLET  END OF 24" CMP
* /-	
/	No sc
/ /	
/	
T.	
	BURVE SURVE
	WARNER R. WRIGHT
NOTE: DISTANCES ARE SLOPE MEASURE	1 4050
NOTE: DISTANCES ARE SLOPE MEASURE	OWN PARTY
	LIST CORRERS TO BE INDEXED
I HEREBY CERTIFY THAT THE SURVEY WORK WAS COMPLETED WAS PREPARED BY ME OR UNDER MY DIRECT PERSONAL SU	PERMISION AND THAT
I AN A DULY REGISTERED LAND SURVEYOR UNDER THE LAW	S OF THE STATE OF IOWA N 1/4 31 84N 3E
Nation S. Chight	
DATE:	5
•	
	MONUMENT RECORD
IIW ENGINEERS &	
SURVEYORS P.C.	TOWNSHID: MACHORETTA
3210 ST.JOSEPH DR DUBUQUE,IA 52001 318556-246	DATE: 10 11 (27) FIELD PROL INDEX

FILE NO **0048:21** BOOK\_/\_ PAGE\_<u>&.8.9</u>

1996 OCT 11 AM 10: 07

SHIRLY RITEHOUR
JACKSON COUNTY, IOWA
RECORDER

## AFFIDAVIT OF CORRECTION


STATE OF IOWA )
COUNTY OF JACKSON) SS

Doc. 1 of 3

- I, Dennis R. Kunze, an employee of the Department of Transportation, State of Iowa \_\_\_\_\_\_state as follows:
- 1. That I am a duly Licenced Land Surveyor under the laws of the State of Iowa and that I prepared an original document known as United States Public Section Corner Certification and Land Corner Survey\_in Section 31, Township 84 North, Range 3 East of the 5th P.M. As recorded in the records of the Jackson County Recorder, as File No. 1215 Book 1, Page 63
- 2. That several errors in the data shown on said document have been detected by subsequent examination.
  - 3. That those errors and their corrected values are as follows:
- A. The angle at the N.E. corner of the N.W. 1/4, incorrectly shown as 91°08'09" should be 91°09'00"
- B. The angle at the N.W. corner of the N.E. 1/4, incorrectly shown as 89°11'21" should be 89°01'19"
- C. The angle at the N.E. corner of the N.E. 1/4, incorrectly shown as 91°12'29" should be 91°17'01"
- D. The angle at the N.W. corner of the N.W. 1/4, incorrectly shown as 89°05'20" should be 89°09'53"
- E. The angle at the S.E. corner of the N.W.1/4, incorrectly shown as 89°22'44" should be 89°17'14"
- F. The angle at the S.W. corner of the N.E. 1/4, incorrectly shown as 90°37'16" should be 90°42'46"
- G. The angle at the N.W. corner of the S.E.1/4, incorrectly shown as 89°22'44" should be 89°17'14"
- 11. The angle at the N.E. corner of the S.W. 1/4, incorrectly shown as 90°37'16" should be 90°42'46
- I. The angle at the S.E. corner of the S.W. 1/4, incorrectly shown as 89°11'05" should be 89°05'35"
- J. The angle at the S.W. corner of the S.E. 1/4, incorrectly shown as 90°35'37" should be 90°41'07"
- K. The distance along the north line of the N.W.1/4, incorrectly shown as 2547.83' should be 2539.30'
- L. The distance along the north line of the N.E.1/4, incorrectly shown as 2632.20' should be 2640.71'
- 4. That said corrected values are shown on the revised section corner certification document marked at the top center, "(Filed For Correction)", and by this reference to said document, shall be made a part hereof.
- 5. That I make this affidavit in order that the same may be filed for record under the provisions of Section 354.24 of the Code of Iowa.

FUE	9	7	(	30	2		
FILE		i		3	14		
	APR				-		
SI JACK	HRLY SON	RIT COU	ENC	UR '. In	w La	46	00

RECORDER DENNIS R. KUNZE BOX 3150 CEDAR RAPIDS, IOWA 52406-3150 319-364-0235 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE LAND SURVEY MONUMENTS SITUATED IN SECTION 31, TOWNSHIP 84N, RANGE 3E , OF THE 5TH PRINCIPAL MERIDIAN JACKSON COUNTY IOWA. PREVIOUSLY RECORDED IN BOOK 1 PAGE 291 IN COUNTY RECORDER'S OFFICE. (Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) MONUMENT DESCRIPTION AND REMARKS: S1/4 CORNER SEC. 31 T84N R3E RESET CONCRETE MONUMENT 3" DEEP ROW/REF PT. STA 1210+56.98 & 150' IRON PIN W/IDOT CAP NOTE: CORNER IS 67.90' LEFT OF STA 1210+14.13 -X-- - FENCE S.C.M. - STANDARD CONCRE MONUMENT - POWER POLE - SECTION CORNER



Ihereby certify that this land surveying document was prepared by me or under my direct personal supervision and that lam a duly licensed Land Surveyor under the laws of the State of lowa.

DENNIS R. KUNZE

License number \_\_\_10679

My license renewal date is December 31, 1998

Pages or sheets covered by this seal:

LAND CORNERS TO BE RECORDED

Corners

Section

Twp.

S1/4 CORNER

84N

3E

Range

FILE NO . PAGE 394

99 SEP -3 AM 10: 12 Ju

DENNIS R. KUNZE

BOX 3150 CEDAR RAPIDS, 10WA 52406-3150 JACKSON COUNTY, 10WA 64-0235
UNITED STATES PUBLIC LAND SURVEY CORNERCORER TIFICATE

1 page 1	OF		
LAND SURVEY MONUMENTS SITUATED IN SE	CTION	31 , TOWNSHIP	84 , RANGE
, OF THE 5TH PRINCIPAL	MERIDIAN _	1401/001	COUNTY IOWA.
PREVIOUSLY RECORDED IN		IN COLINIY	RECORDER'S OFFICE.
(Show reason for preparing this certificate, the evidence corner positions and manumentation found or placed.)  MONUMENT DESCRIPTION AND REMARKS:	document numb and detailed p	er, etc.) rocedures used in establishing the	NECONDER S OFFICE.
NI/A CORNER SECTION 31-T84N-R3E  IRON PIN WITH YELLOW CAP NO. 7983  SET "X" NAILS IN CORNER POST IRON PIN WITH YELLOW CAP NO. 7983  FOUND "X" NAILS POWER POLES  FOUND YELLOW IIW CAP NO. 4850 3" DEEP	-9 — 226.13 — SET 5/8** RED PLA MARKED F	CORNER OF THE SEM NWM SECTION 31-T84N-R3E  88.01  88.01  23.19  FOUND 5/8- REBAR MIDWAY ON LINE N-S D PLASTIC CAP MARKED PLS 10679	N
SE CORNER OF THE NE1/4 SW1/4 SECTION 31-T84N-R3E  "X' NAILS OF STA 1223+42.50±  WOOD POST  WITH IDOT CAP  SET 5/8" X 30" REBAR MIDWAY ON LINE N-S WITH RED PLASTIC CAP MARKED PLS 10679 SET REFERENCE POINT SIGN I' WEST OF CORNER	IRON PINS WITH ALUM, IDOT CAP PINS ARE 2' EAST OF FENCE	DRNER SECTION 31–T84N–R3E    10	TH -X- = FENCE  S.C.M. = STANDARD

was prepared by me or under my direct supervision and that I am a duly license. Surveyor under the lows of the State of the DENNIS	ed Land of Iowa. of 1999 Date
--	--

LAND CORNE	RS TO BE	RECOR	IDED
Corners	Section	Twp.	Range
NI/4 CORNER	31	84N	3E
NE CORNER SEI/4 NWI/4	31	84N	3E
SE CORNER NEI/4 SWI/4	31	84N	3E
SI/4 CORNER	31	84N	3E