UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE SLS1 9-90

OF


3E	numents situated in S	ection7 incipal Meridian,	Jackson Town	ship84N	, Range County, Iowa.
Previously record	ed in	•		in County I	Recorder's Office
Monument Descri	paring this certificate, the laced.) option and Remarks:	cument number, etc.) c evidence and detailed	procedures used in e	SAME AND A SECTION OF THE SAME AND A SECTION OF THE SAME AND SAME	
For Owen	survey. Found i	ron rod at loca	ion called fo	or in survey pla	it recorded
	on County Records				
Monument	is near edge of	rock quarry in	graveled area	subject to truc	ek traffic.
			6		
(Show a minimum of recovery of the corner	three reference ties to du	PLAN - V	TEW relevant monuments	and physical conditio	ons that will enable
		Center	line Rockdale	Road (extended	from east)
	section line Z	~	outh road dit		Trom Casty
		237.3'	7		j
quarry () water filled)	spike in 3" tree	, , , , , , , , ,	spike in powe about 3' about	er pole Ve ground	
p rock bluff	34.6. Opt	SW corner	graveled a	area J	
:	spike in 12" cottonwood				
was prepared by me o	ne survey work was com r under my direct persor I land surveyor under the	al cuparvision and that	Corners		dexed Twp Range B4N BE
Signature: Name typed or printed: Date: 3/23/92	Thomas C. Tucke Reg. No.		- ,	70 F 2	419
	THOMAS C.		۵	800KPAG	BE 80 M 8: 37
SEAL SEAL	TUCKER 5339			SHIRLY RITE JACKSON COUN RECORDE	TY, IOWA
- Takkakak	OWA		ВООР	Zw.	J.

2-19-97 Convector Centificari Book 1 page 308

. Or	
Land Survey Monuments situated in Section	Township 84N, Range
usly recorded in NOT APPLICABLE	County, Iowa. in County Recorder's Office.
(Show reason for preparing this certificate, the evidence and detailed p mentation found or placed.) Monument Description and Remarks: NO EVIDEN	rocedures used in establishing the corner positions and monu-
CORNER LOCATION OF AN EXISTIN	OG STONE OR IRON CORNER STAKE.
CENTER SECTION WAS SET AT THE I	STERSECTION OF A FEIXE TO THE NORTH
WITH A FENCE TO THE WEST. E1/4	CORNER WAS SET
	301
-	
(Show a minimum of three reference ties to durable physical objects, receivery of the corner.)	IEW clevant monuments and physical conditions that will enable
NAIL IN GATE POST NAIL IN GATE POST NAIL IN CORNER POST RAIL ROA	13.91
SET: 98 REBAR FENCE WITH CAP NAIL SE #7983	DER 18 1. AS' SOUTH EXISTING CORNER POST
COSTEL GETTON	
SET: 5/8" REBAR WITH CAP #7983	ROAD DUMBER SIGN ROAD DUMBER SIGN ROAD DUMBER SIGN RECISER 9: 44 RECISER 9: 4
I hereby certify that the survey work was completed and this certificate was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of lowa.	List Corners to be Indexed Corners Section Twp Range
Signature: AMES L. EGGER P.E. L.S.	CENTER 7 84N 4E
Date: DEC. 10, 1996 Reg. No. 7983	E1/4 7 84N 4E
SEAL 7983	W/4 8 84N 4E
LAID STATE OF THE PARTY OF THE	

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF



UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 7

BEAST, of the Fifth Principal Meridian, Nange, Range Township JACKSON County, Iowa. Previously recorded in NONE in County Recorder's Office. (book, page, document number, etc.)
(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) Monument Description and Remarks: THE TWO CORNERS WE SET WERE LAND BOUNDARY CORNERS, BUT THE IOWA BOARD SURVEYING 7451-10 CORNERS, AN OPINION THIS SURVEYOR BUT NONE IN A DECISION RENDERED BY THE POORD AUG. 12, 199 DATED PLAN - VIEW (Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.) _ MEASURE MENTS ARE SLOPE DISTANCES SLOPE MEASUREMENTS "X" NAILS IN SOUTH SIDE OF 18"WALLOUT TREE FENCES SET 5/8" IRON 40 ROD WITH YELLOW PLASTIC CAP. 7 8 BOCK 8"X8" RAIL TIE BRACE POST "X" NAILS IN "X" NAILS IN SOUTH SIDE WEST FACE CIWT "AS 70. BXB" RAIL HICKORY TREE POSTS "X" NAIL Certificate SET S/A"IRON ROD WITH YELLOW PLASTIC HSF CAP WOOD FRAME HSE. WITH CONC. BLK. NW COE-SE1/4-SE1/4 FOUNDATION SEC. 7-84-3 I hereby certify that the survey work was completed and this certificate ST 1257 was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of List Corners to be Indexed Corners Section Twp Range Signature: NE COR SE1/4-SE1/4 Sec 7-84-Rcg. No NW COR SEVA-SEVA SEC. 7-84-JAMES L. EGGER SEAL 7983 AWO! AM IO:

FILE NO 03-3656

03 JUN 19 AM 9:51

PHYLLIS M. GERLACH JACKSON COUNTY, IOWA RECORDER

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 7, Township 84 North, Range 3 East of the Fifth Principal Meridian, Jackson County, Iowa.

Previously recorded (NONE OF RECORD)

(BOOK, PABE / INST. NO. / CABINET, SLIDE)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: A 1/2 REBAR W CAP #10135 WAS FOUND AT THE SW CORNER OF THE NW FRL 1/4 OF THE NW FRL 1/4 OF SECTION 7, TB4N, R3W. THE PIN WAS TIED AND USED AS THE CORNER.

THE SE CORNER OF THE NM1/4 OF THE NE1/4 OF SEC.7, TB4N, R3E WAS ESTABLISHED AT THE INTERSECTION OF


OCCUPATION FENCES LOCATED NORTH, SOUTH, EAST AND WEST OF THE CORNER. THE SW CORNER OF THE NW 1/4 OF THE NE1/4

OF SEC.7, T84N, R3W WAS RE-ESTABLISHED BY INTERSECTION THE SOUTH LINE OF A PARCEL ILLUSTRATED ON A PLAT OF SURVEY

FILED IN BOOK 1-G, PAGE 47 WITH A LINE PROJECTED FROM THE CENTER OF SAID SECTION 7 THROUGH THE FENCE INTERSECTION AT THE SW CORNER OF THE NW1/4 OF THE NE1/4 OF SAID SECTION 7.


PLAN - VIEW


(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



200th AVE.

SW CORNER NW FRL 1/4, NW FRL 1/4 SEC.7, T84N, R3W FOUND 1/2" REBAR W/ CAP #10135





I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

David P. Schneider P.L.S. #14417 Pate:/


My license renewal date is December 31, 2003.

Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER

Land Surveying & Planning, Inc.

P.O. Box 105 Peosta, Iowa 52068 Ph. #563-556-9055 Fax#563-556-9054



L130 (201 1161 3	CO DC THUCK	\Cu
Corners	Section	Тwp	Range
SW CORNER NW FRL 1/4. NW FRL 1/4	7	84N	3E
SW CORNER NW1/4, NE1/4	7	84N	3E
SE CORNER	7	84N	3E

NAILS IN

YELLOW CAP

NW1/4, NE1/4

03 JUN 19 AM 9:51

PHYLLIS M. GERLACH JACKSON COUNTY, 10WAK RECORDER Fee 6.

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF Land Survey Monuments situated in Section 7, Township 84 North, Range 3 East

of the Fifth Principal Meridian, Jackson County, Iowa.

Previously recorded _ (NONE OF RECORD)
(BOOK, PAGE / INST. NO. / CABINET, SLIDE)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: THE N1/4 CORNER OF SEC. 7. TB4N, R3E WAS RE-ESTABLISHED AT THE BASE OF RUSTED OFF ANGLE IRON CORNER POST. THE NE CORNER OF THE NW1/4 OF THE NE1/4 OF SEC.7, T84N, R3E WAS


ESTABLISHED AT THE INTERSECTION OF OCCUPATION FENCES NORTH, SOUTH, EAST AND WEST OF THE CORNER

THE NE CORNER OF SEC.7, TB4N, R3E WAS RE-ESTABLISHED BY DOUBLING THE DISTANCE FROM THE N1/4 CORNER OF SECTION

THROUGH THE NE CORNER OF THE NW1/4 OF THE NE1/4 OF SECTION 7 AND PLACED IN THE EAST-WEST OCCUPATION FENCE

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed land Surveyor under the laws of the State of Iowa.

David P. Schneider P.L.S. #14417 Date:

My license renewal date is December 31, 2003. Pages or sheets covered by this seal: THIS SHEET ONLY

Land Surveying & Planning, Inc.

P.O. Box 105 Peosta, Iowa 52068 Ph. #563-556-9055 Fax#563-556-9054



List	Corners	to be Inde	xed
Corners	Section	Twp	Range
N1/4	7	84N	ЗЕ
NE CORNER NW1/4, NE1/	7	84N	3E
NE CORNER	7	84N	3E

FILE NO 04-1247 900K 2 PAGE 241

04 MAR 29 AM 7: 11

PHYLLIS M. GERLACH

JACKSON COUNTY, 10WA

RECORDER FE# 11

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 7, Township 84 North, Range 3 East of the Fifth Principal Meridian, Jackson County, Iowa.

Previously recorded CENTER - S.C.C. BOOK 1, PAGE 30B, SE CORNER OF NW1/4, SE1/4 - S.C.C. BOOK 1, PAGE 39B.

CROOK, PAGE / INST. NO. / CABINET, BLIDED

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: A 5/8" REBAR WITH CAP ₱7983 WAS FOUND AT THE CENTER OF SEC.7.

T84N, R3E AS ILLUSTRATED IN SECTION CORNER CERTIFICATE FILED IN S.C.C. BOOK 1, PAGE 308. THE CORNER WAS REFILED

TO ILLUSTRATE ADDITIONAL TIES

THE NE CORNER OF THE NW1/4 OF THE SE1/4 OF SEC.7, T84N, R3E WAS ESTABLISHED AT THE MIDPOINT OF A LINE FROM THE

CENTER TO THE E1/4 CORNER OF SAID SECTION 7.


A 5/8" REBAR WITH CAP #7983 WAS FOUND AT THE SE CORNER OF THE NW1/4 OF THE SE1/4 OF SEC.7, T84N, R3E AS

ILLUSTRATED IN SECTION CORNER CERTIFICATE FILED IN S.C.C. BOOK 1, PAGE 398. THE CERTIFICATE WAS FILED TO

ILLUSTRATE ADDITIONAL TIES WHICH WERE ADDED.

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed land Surveyor under the laws of the State of Iowa.

David P. Schneider P.L.S. #14417 Date:

My license renewal date is December 31, 2005.
Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER

Land Surveying & Planning, Inc.

P.O. Box 105 Peosta, Iowa 52068 Ph. #563-556-9055 Fax#563-556-9054



List	Corners	to be Index	ed
Corners	Section	Тыр	Range
CENTER	7	84N	3E
NE CORNER NW1/4, SE1/	7 4	84N	3E
SE CORNER NW1/4, SE1/	7 4	84N	ЗE

JOB NO. 597

Book 2 Page 241

FILE NO OY-

04 MAR 29 AM 7: 11

PHYLLIS M. GERLACH JACKSON COUNTY, 10WA DO RECORDER FEET 11.

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 7, Township 84 North, Range 3 East of the Fifth Principal Meridian, Jackson County, Iowa.

Previously recorded SW CORNER; BOOK 1, PAGES 119 AND 120

(BOOK, PAGE / INST. NO. / CABINET, SCIDE)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) Monument Description and Remarks: A 5/8" REBAR WAS FOUND AT THE SW CORNER OF SEC.7, T84N, R3E AS


INDICATED ON THE SECTION CORNER CERTIFICATE FILED IN S.C.C. BOOK 1 AT PAGES 119 AND 120. BECAUSE MORE TIES WERE ADDED


THE S1/4 CORNER OF SEC.7, T84N, R3E WAS ESTABLISHED ON LINE FROM THE SE CORNER TO THE SW CORNER OF SAID SECTION 7 AND IN LINE WITH AN OCCUPATION FENCE LOCATED NORTH OF THE CORNER

PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)







SET 60d SPIKE IN CLIP OF T-POST SET 'X' NAILS IN FENCE POST SET 'X' NAILS IN BRACE POST ⁶⁰.37.

S1/4 CORNER 75.82. SEC.7, T84N, R3E SET 1/2" REBAR W/ YELLOW CAP #14417

×O-

O SET 'X'
NAILS IN
CORNER
POST 20

I hereby	certify and the	that	this	land	survey	ing	docum	ent	was
me or und am a duly State of	v license	rect ed lan	persi	nnal e	linervi	einn	and .	that	· T

David P. Schneider P.L.S. #14417

My license renewal date is December 31. Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER

Land Surveying & Planning, Inc.

P.O. Box 105 Peosta, Iowa 52068 Ph. #563-556-9055 Fax#563-556-9054



	List	Corners	to	be	Indexe	d
Corners		Section		T	4p	Range
SW		7	84N		3E	
S1/4		7	84N		3E	

JOB NO. 597

FILE NO . 04-1253 PAGE 247

04 MAR 29 AM 7: 12

PHYLLIS M. GERLACH JACKSON COUNTY. 10WA* 00 RECORDER

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 7. Township 84 North, Range 3 East of the Fifth Principal Meridian, Jackson County, Iowa. Previously recorded ___

SCC BOOK 2, PAGE 167 (ALL)
(BOOK, PAGE / INST. NO. / CABINET, SLIDE)

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) Monument Description and Remarks: A 1/2" REBAR W/CAP #10135 WAS FOUND AT THE SW CORNER OF THE NW

FRL 1/4 OF THE NW FRL 1/4 OF SECTION 7, T84N, R3W. THE PIN WAS TIED AND USED AS THE CORNER.

THE SE CORNER OF THE NW1/4 OF THE NE1/4 OF SEC.7, TB4N, RJE WAS ESTABLISHED AT THE INTERSECTION OF


OCCUPATION FENCES LOCATED NORTH, SOUTH, EAST AND WEST OF THE CORNER. THE SW CORNER OF THE NW 1/4 OF THE NE1/4

OF SEC.7, T84N, R3W WAS RE-ESTABLISHED BY INTERSECTION THE SOUTH LINE OF A PARCEL ILLUSTRATED ON A PLAT OF SURVEY


FILED IN BOOK 1-G, PAGE 47 WITH A LINE PROJECTED FROM THE CENTER OF SAID SECTION 7 THROUGH THE FENCE INTERSECTION AT THE SW CORNER OF THE NW1/4 OF THE NE1/4 OF SAID SECTION 7.


PLAN - VIEW

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)



SW CORNER NW FRL 1/4, NW FRL 1/4 SEC. 7, TB4N, R3W FOUND 1/2" REB W/ CAP #10135 REBAR





I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa.

David P. Schneider P.L.S. #14417 My license renewal date is December 31, 2005.

Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER

Land Surveying & Planning, Inc.

P.O. Box 105 Peosta, Iowa 52068 Ph. #563-556-9055 Fax#563-556-9054



List	Corners	to be Index	ed
Corners	Section	Тwр	Range
SW CORNER NW FRL 1/4 NW FRL 1/4	7	84N	3E
SW CORNER NW1/4, NE1/	4 7	B4N	ЗE
SE CORNER NW1/4, NE1/	7	84N	3E

JOB NO. 186

P 247 R.N

Document 16-820

Book 2016 Page 820 Type 15 001 Pages 1 Date 3/15/2016 Time 10:46 AM Rec Amt \$7 00

ARLENE SCHAUF, RECORDER/REGISTRAR JACKSON COUNTY IOWA

Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 128 Farley, Iowa 52046 563-744-3631

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF


Land Survey Monuments situated in Section 7, Township 84 North, Range 3 East of the Fifth Principal Meridian, Jackson County, Iowa.

(NONE OF RECORD)

(ROOK PARE / PARE /

MONUMENT DESCRIPTION AND REMARKS: THE NE CORNER OF THE SW FRL1/4 OF THE NW FRL1/4 OF SECTION 7,
T84N, R3E WAS ESTABLISHED USING EXISTING OCCUPATION EVIDENCE LOCATED SOUTH AND EAST AS WELL AS IN LINE WITH
THE SOUTH LINE OF A PARCEL OF LAND ILLUSTRATED ON A PLAT OF SURVEY FILED IN BOOK 1-6, PAGE 47 LOCATED TO THE
WEST AND NORTH. THE SE CORNER OF THE SW FRL1/4 OF THE NW FRL1/4 OF SECTION 7, T84N, R3E WAS ESTABLISHED ON
A LINE FROM THE W1/4 CORNER TO THE CENTER OF SAID SECTION 7 AND IN LINE WITH EXISTING OCCUPATION FENCES NORTH
OF THE CORNER.

PLAN - VIEW



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed land Surveyor under the laws of the State of Iowa.

David P. Schneider P.L.S. #14417 Date:

Ty license renewal date is December 31, 2017.

Pages or sheets covered by this seal: THIS SHEET ONLY

SCHNEIDER Land Surveying & Planning, Inc. P.O. Box 128 Farley, Iowa 52046 Ph. #563-744-3631 Fax#563-744-3629



List	Corners	to be	Indexe	d
Corners	Section	TW	р	Range
NE CORNER SW FRL1/4, NW FRL1/4,	7	84	IN	ЗE
SE CORNER SW FRL1/4, NW FRL1/4	7	84	IN .	3E

JOB NO. 1884