

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

AND SURVEY MONUMENTS SITUATED IN SECTION 3 EAST , OF THE 5TH PRINCIPAL MERI	DIANJACKSON	NORTH , RANGE COUNTY IOWA
REVIOUSLY RECORDED IN DOES NO (book, page, docum	and ment of the state of the st	NTY RECORDER'S OFFIC
Show reason for preparing this certificate, the evidence and do priner positions and monumentation found or placed.) IONUMENT DESCRIPTION AND REMARKS:	etalled procedures used in establishing the	
RE-REFERENCE CORNERS FOR EXCESS	S RIGHT OF WAY SALE ANI) ABANDONMENT
(Show a minimimum of three reference ties to durable proceed that will enable recovery of the corner.)	→ VIEW physical objects, relevant monuments and phy	raical
N1/4 COR. SEC. 9-84-3E	NE COR. SEC. 9-84-3E	
NAIL IN STEEL FC. POST	X" HAILS IN 24"	9
40.30' 42,04'		40
SHOULDER	52.14'	
COUNTY	"x" HALS	BR.PO.
NOAD "x" N	ALS BR.PO. 11.72' 8.65'	—×-
91.05' 46.03'	1.73'	N.
56.27 52.90'	53.37'	
"x" NAILS N PWR. PO. NAIL IN STEEL FC. POST	"x" HAILS IN 36" (CO)	
SET 5/8" × 26" RE-BAR	FOUND ROUND CONC. MONU	.
	ABOVE GROUND AND 7 FEET SOUTH OF FENCE	
,		
	e e	
		D.
EBY CERTIFY THAT THIS LAND SURVEYING DOCUMENT WAS IRED BY ME OR UNDER MY DIRECT PERSONAL SUPERVISION HAT I AM A DULY REGISTERED LAND SURVEYOR UNDER THE OF TOWA.	LAND CORNERS TO B	E RECORDED
OF THE STATE OF TOWA.	Corners Section Twi	
TURE:	N1/4 9 84	
DENNIS R. KUNZE	NE 9 84	3E
7 - 27 - /99} REG. NO. 10679	FILE NO 000240	
DISTRATION EXPIRES DECEMBER 31	BOOK PAGE 153	
R R	1993 JUL 27 PM 1: 46	
THE TENED	SHIRLY RITEHOUR	
1019	II SHILL TOTAL TOWN	






JACKSON COUNTY, IOWA
RECORDER

1997 HAY 19 AM ID: 21

SHIRLY RITENDUR JACKSON COUNTY, ICHA PERSHIYER 1. (The 319-364-0235 DENNIS R. KUNZE BOX 3150 CEDAR RAPIDS, IOWA 52406-3150 319-364-0235 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF LAND SURVEY MONUMENTS SITUATED IN SECTION 9 TOWNSHIP 84 NORTH , RANGE 3 EAST , OF THE 5TH PRINCIPAL MERIDIAN ______ JACKSON _____ COUNTY IOWA. PREVIOUSLY RECORDED IN DOES NOT APPLY IN COUNTY RECORDER'S OFFICE. (book, page, document number, etc.)
(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.) MONUMENT DESCRIPTION AND REMARKS: S1/4 COR. SEC. 9-84-3E - ±9.0' -ARGEST TREE -10.70' -FOUND 19"X8"X6" LIMESTONE 8" DEEP. SET BRASS PLUG IN CENTER OF STONE SET 5/8" IRON PIN ON EAST SIDE OF STONE FOR METAL LOCATER USE ONLY. SET REF. POINT SIGN & POST "EAST -X- - FENCE S.C.M. - STANDARD CONCRETE MONUMENT - POWER POLE - SECTION CORNER - TREE




LAND	CORNERS TO	BE REC	ORDED
Corners	Sectio	n Twp	. Range
S1/4	9	84	3E

BOOK 1 PAGE 320

of the Fifth Principal Meridian (5th PM), Jackson County, Iowa. (Not Previously Recorded)

The Monuments were placed at the Southeast corner, of the Northwest Quarter (NW 1/4), of the Northwest Quarter (NW 1/4), and the Southwest corner of the Northwest Quarter (NW 1/4), of the Northwest Quarter (NW 1/4), of Section 9 per the description below.

Corner locations were established at prorate locations using existing monuments, fences and occupation lines within this and adjoining Sections.



Project No. 2002190

I hereby certify that the survey work was completed and this land surveying document was prepared by me or under my direct personal supervision and hat I am a duly registered land surveyor under the laws of the State of lowa.

Signature:

William E. Holt
Iowa Registration No. 14105
My Registration Renews on December 31, 2002
Dated this 12 b day of September, 2002 C.E.

	Cor	ners	to	be	Indexed	
Corner		Section	on		Township	Range
SE Corner NW1/4 NW	1/4	9		ř	84N	3E
SW Corner NW1/4 NW	1/4	9			84N	3E


03 OCT 13 PM 12: 35

PHYLLIS M. GERLACH JACKSON COUNTY. IOWA
Prepared by Thomas C. Tucker, L.S., 3851 Eagle Hts., Clinton, IA 52732 REG9RDAB-5392)

LOD SLS1 9-94 UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 9 E, of the Fifth Principal Meridian,	JACKSON Township 84 N , Range
Previously recorded in	N.A. in County Recorder's Office.
(Show reason for preparing this certificate, the evidence and detailed mentation found or placed.) Monument Description and Remarks: CENTER OF SI	d procedures used in establishing the corner positions and monu- ECTION: See plat of survey in Bk. 1D-p.78.
Found 5/8" rerod at location noted in plat. D	
	: Using fences and field measurements set a
5/8" x 24" rerod and referenced as shown. SW (
in line with center of section and the \mathbb{E}^1_{4} corn	
Referenced as shown. All 5/8"x24" rerods set 1	have orange plastic caps with #5339.
(Show a minimum of three reference ties to durable physical objects recovery of the corner.) CENTER OF SECTION 9 18.27' to nail in fence post ROW rail 162.27' -N89°59'20"E 1328.62' © Found 5/8" rerod Set 5/8" rerod Set 5/8" rerod 1 corner post	VIEW I relevant monuments and physical conditions that will enable monu
I hereby certify that the survey work was completed and this land surveying document was prepared by me or under my direct person supervision and that I am a duly registered land surveyor under the laws of the state of Iowa Signature: Thomas C, Tucker Date: 10/13/03 Reg. No. 5339 My registration renewed date is December 31, 2003 SEAL 5339	List Corners to be Indexed Corners Section Twp Range CENTER OF 9 84N 3E SEC. 9, Etaureta, SWOfSEtaureta,
TROP SUND STATE	D 1 2 Prog 201



Prepared by: SCHNEIDER Land Surveying and Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 563-556-9055

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section 9, Township 84 North, Range 3 East of the Fifth Principal Meridian, Jackson County, Iowa.
Previously recorded SE CORNER, NW1/4, NW1/4 - SCC BOOK 1.

(BOOK, PAGE / INST. NO. / CABINET, SLIDE)

PAGE 579

(Show reason for preparing this certificate, the evidence and detailed procedures used in establishing the corner positions and monumentation found or placed.)

Monument Description and Remarks: A 1/2" REBAR WAS FOUND AT THE W1/4 CORNER OF SEC.9, T84N, R3E THE CORNER WAS ILLUSTRATED ON A SURVEY PLAT FILED IN BOOK 1-E, PAGE 3. THE MONUMENT WAS USED AS THE W1/4


CORNER AND REFERENCE TIES WERE PREPARED.


A 5/8" REBAR WITH CAP #14105 WAS FOUND AT THE SE CORNER OF THE NW1/4 OF THE NW1/4 OF SEC.9, T84N, R3E AS ILLUSTRATED IN A SECTION CORNER CERTIFICATE FILED IN S.C.C. BOOK 1, PAGE 579. THE CORNER WAS RETIED BECAUSE ONLY TWO TIES REMAINED.

PLAN - VIEW


F

(Show a minimum of three reference ties to durable physical objects, relevant monuments and physical conditions that will enable recovery of the corner.)





SE CORNER NW1/4, NW1/4 SEC.9, T84N, R3E FOUND 5/8" REBAR W/ CAP #14105



I hereby certify that this land surveying document was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of Iowa

David P. Schneider P.L.S. #14417 Date: My license renewal date is December 31, 2005.

Pages or sheets covered by this seal: THIS SHEET ONLY

Land Surveying & Planning, Inc. P.O. Box 105 Peosta, Iowa 52068 Ph. #563-556-9055 Fax#563-556-9054 Peosta, Iowa 52068



ist	Corners	to	be	Indexed	ď
	Section		T	4 p	Range
	9		84	N	ЗЕ
	ist	Section	Section	Section T	₩

SE CORNER **84N** 3F NW1/4, NW1/4

JOB NO. 597

P- a- 239

Document 05-3100

Book 2 Page 371 Type 06 023 Pages I Date 8/05/2005 Time 8:29 AM Rec Amt \$7.00

PHYLLIS M. GERLACH, RECORDER JACKSON COUNTY IOWA

Landmark 511 South 4th Street Clinton, 1A 52732

SLSI 9-90

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE OF

Land Survey Monuments situated in Section9	Township 84 N Range
3 E, of the Fifth Principal Meridian,	
Previously recorded in N/A , in JACKSON	
(Show reason for preparing this certificate, the evidence and detailed pro-	cedures used in establishing the corner positions and monu-
mentation found or placed.)	
Monument Description and Remarks: CENTER OF SE 1/4 SEC.	
ANCIENT FENCE LINES NORTH, WEST, EAST AND SOUTH. SEARC	H ARE 10 FEET.
	PROJECT NO. 04-05-376
(Show a minimum of three reference ties to durable physical objects, r	VIEW elevant monuments and physical conditions that will enable
recovery of the corner.)	1-1-1-1-
	- - - -
OF SEC 9, PER COR. CERT AT BOOK	
2 PAGE 201	
	and the second s
	\\.
	Ų.
82	
22.5.7.9.7.9.7.9.7.9.7.9.9.7.9.9.7.9.9.7.9.9.7.9	
CENTER OF SE 1/4 OF SEC. 9,	Ņ
1/2" ROUND IRON ROD STAKE SET	
REF: 9.24' - N, P-K SPIKE IN TOP OF W	OOD FENCE POST
0.39' - SE, P-K SPIKE IN TOP OF 20.86' - E, P-K SPIKE IN TOP OF	
20.00 E, T K 31 KE III 101 01	TOOD FERGE FOOT
-X-X-X- = EXISTING ANCIENT	FENCE LINE
*	
I hereby certify that this land surveying document	List Corners to be Indexed
was prepared and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed land	*
surveyor under the laws of the State of Iowa.	Corners Section Twp Range
De 19/1/2 16/6200	CENTER OF 9 84 N 3 E
Harry J. Goldard Date	SE 1/4
My license is subject to renewal on Dec. 31, 2006	9
License No. 15524	
arii AND Sunn	
Only those copies of this page	
signed in red color and displaying surveyors original	
HARRY J. O Scal are to be considered certified official copies.	Book 2 Page 371



Book 2 Page 690 Type 15 001 Pages 1 Date 11/30/2009 Time 3:20 PM Rec Amt \$9.00

ARLENE SCHAUF, RECORDER/REGISTRAR JACKSON COUNTY IOWA

repared by Thomas C. Tucker, L.S., 3851 Eagle Hts., Clinton, IA 52732 (563-242-5392)

SLSI 9-94

UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE

OF

Land Survey Monuments situated in Section 9 3 E, of the Fifth Principal Meridian, Previously recorded in BK. 2, p. 201	, Towns	ship	84 N	, Range
Previously recorded in		in Cou	inty Recorde	er's Office.
(Show reason for preparing this certificate, the evidence and detailed promentation found or placed.) Monument Description and Remarks:				
SW CORNER OF SE4-NE4: Found iron rod w/orange	nlastic car	#5330 Ms	ade this co	ornor
certificate because one reference tie was lost				THET
was removed and relocated.	and one east	city case,	vest rence	

(Show a minimum of three reference ties to durable physical objects, relerecovery of the corner.)	CW vant monuments	and physical co	nditions that w	rill enable
fence post 8.2'	previous feNew f 0.15' to nai	ence location 'ence l in brace	,	noved)
I hereby certify that the survey work was completed and this land surveying document was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of Iowa	Comers SW of SE ¹ / ₄ -NE ¹ / ₄	List Corners to Section	be Indexed Twp	Range 3E
Signature: Thomas C. Tucker Name typed or printed: Thomas C. Tucker	,			
Date: 11/23/09 Reg. No. 5339				
My registration renewal date is December 31, 2009				
SEAL 5339	Book 2	Page	690	
GR SLAND SUP				